



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

March 16, 2006

Supervisor

LRZ

Mine Name: Moenkopi Moca

Operator Name: Bruce Hansen Stone Quarries
1345 South Stewart Drive
P.O. Box 341
Kanab, Utah 84741-0341

Permit number: S/025/021

Inspection Date: February 28, 2006

Time: 8:30 AM

Inspector(s): Doug Jensen

Other Participants: Bruce Hansen, Noal Hansen

Mine Status: Active

Weather: Rainy, cool

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated Comment Enforcement

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Site familiarization and the operator has expressed as desire to expand his quarry. I needed to GPS the present site.

Inspection Summary:

I met Bruce and Noal at their yard east of Kanab then drove to the site. The site is located ~5.7 miles east of the Johnson Canyon road then turn right and travel 1½ miles into the site.

I discussed the expansion with the operators so that I would have an idea of how the quarry would expand. After the discussion I GPS'd the quarry and took photos.

The operator is presently cutting the sandstone into large blocks by drilling and blasting the blocks loose. The blocks are then moved into their yard near Kanab where the blocks are cut utilizing a large rock saw.

The site was clean and appeared to be well run with attention to how the site would be left when the mining was completed.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspection Date: February 28, 2006; Report Date: March 16, 2006
Page 2 of 2
S/025/021

Inspector's Signature



Date: 3/16/06

dj:pb

cc: Noal Hansen, Hansen Quarries
John Blake, SITLA

Attachment: GPS & Photos

O:\M025-Kane\S0250021-MoenkopiMoca\inspections\02282006insp.doc



MOENKOPI MOCA QUARRY


Mine Number: S0250021
Mine Name: Moenkopi Moca
Township 32 S Range 04 W Section 32 SLBM

Inspection Date Feb. 28, 2006
Map Produced by DKS

Acres Disturbed	1.73
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	1.73
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

- Legend**
All items symbolized in legend may not be appear on map
- County Boundary
 - Township or range line: location doubtful
 - Access
 - Mine
 - NonMine
 - Section line
 - Section line location doubtful
 - Other
 - Disturbed
 - Regraded
 - Seeded
 - US Route
 - State Route
 - Primary Route
 - Secondary Route
 - Main Dirt Road
 - Unimproved Road
 - Interchange
 - Trail
 - Bond Area
 - STLA Mineral Leases
 - BLMSabteMinerals
 - CommunityPI

DOQ imagery date 2004



Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.